POWER-LITE®

Certainty at The Speed of Light

# INSTALLATION
MANUAL

SURFACE **MOUNT**

BOX

ENM-SMB-B

Step 1

Unlock the cover of the surface mount box with a flat screwdriver.

Step 2

Fix LED driver, battery and PA terminal onto the base. Have battery connected to the driver, draw wires from the driver and connect them to the terminal.

LED DRIVER

BATTERY

Step 3

Knock out the mains power cable entry hole, and fix the base onto ceiling with 4 screws. Connect the cable into terminal, have lamp head fixed onto cover, and safety rope connected, Connect the lamp head cable with driver.

Step 4

Click the cover on the base, and finish installation.